

	Decimal	MM
	$\frac{1}{64}$ — .0156	0.396
	$\frac{1}{32}$ — .0312	0.793
	$\frac{3}{64}$ — .0468	1.190
$\frac{1}{16}$ —	.0625	1.587
	$\frac{5}{64}$ — .0781	1.984
	$\frac{3}{32}$ — .0937	2.381
	$\frac{7}{64}$ — .1093	2.778
$\frac{1}{8}$ —	.125	3.175
	$\frac{9}{64}$ — .1406	3.571
	$\frac{5}{32}$ — .1562	3.968
	$\frac{11}{64}$ — .1718	4.365
$\frac{3}{16}$ —	.1875	4.762
	$\frac{13}{64}$ — .2031	5.159
	$\frac{7}{32}$ — .2187	5.556
	$\frac{15}{64}$ — .2343	5.953
$\frac{1}{4}$ —	.250	6.350
	$\frac{17}{64}$ — .2656	6.746
	$\frac{9}{32}$ — .2812	7.143
	$\frac{19}{64}$ — .2968	7.540
$\frac{5}{16}$ —	.3125	7.937
	$\frac{21}{64}$ — .3281	8.334
	$\frac{11}{32}$ — .3437	8.731
	$\frac{23}{64}$ — .3593	9.128
$\frac{3}{8}$ —	.375	9.525
	$\frac{25}{64}$ — .3906	9.921
	$\frac{13}{32}$ — .4062	10.318
	$\frac{27}{64}$ — .4218	10.715
$\frac{7}{16}$ —	.4375	11.112
	$\frac{29}{64}$ — .4531	11.509
	$\frac{15}{32}$ — .4687	11.906
	$\frac{31}{64}$ — .4843	12.303
$\frac{1}{2}$ —	.500	12.700

	Decimal	MM
	$\frac{33}{64}$ — .5156	13.096
	$\frac{17}{32}$ — .5312	13.493
	$\frac{35}{64}$ — .5468	13.890
$\frac{9}{16}$ —	.5625	14.287
	$\frac{37}{64}$ — .5781	14.684
	$\frac{19}{32}$ — .5937	15.081
	$\frac{39}{64}$ — .6093	15.478
$\frac{5}{8}$ —	.625	15.875
	$\frac{41}{64}$ — .6406	16.271
	$\frac{21}{32}$ — .6562	16.668
	$\frac{43}{64}$ — .6718	17.065
$\frac{11}{16}$ —	.6875	17.462
	$\frac{45}{64}$ — .7031	17.859
	$\frac{23}{32}$ — .7187	18.256
	$\frac{47}{64}$ — .7343	18.653
$\frac{3}{4}$ —	.750	19.050
	$\frac{49}{64}$ — .7656	19.446
	$\frac{25}{32}$ — .7812	19.843
	$\frac{51}{64}$ — .7968	20.240
$\frac{13}{16}$ —	.8125	20.637
	$\frac{53}{64}$ — .8281	21.034
	$\frac{27}{32}$ — .8437	21.431
	$\frac{55}{64}$ — .8593	21.828
$\frac{7}{8}$ —	.875	22.225
	$\frac{57}{64}$ — .8906	22.621
	$\frac{29}{32}$ — .9062	23.018
	$\frac{59}{64}$ — .9218	23.415
$\frac{15}{16}$ —	.9375	23.812
	$\frac{61}{64}$ — .9531	24.209
	$\frac{31}{32}$ — .9687	24.606
	$\frac{63}{64}$ — .9843	25.003
1 —	1.000	25.400

